

Katente West Hostel for Blind and Visually Impaired Pupils – showing the building work required



Front view of the hostel with the matron



One side wall of the hostel which requires plastering and an apron at base of wall



Water tank and girls' side entrance. This wall also needs plastering and an apron



Rear wall which requires plastering. The apron needs to be completed



Inside of the hostel showing the lack of a ceiling



Inside the dormitory with the first 2 VI residents, matron and the School Management Committee